

October 2011 Inspection Report

Browns Town Market Clock

LOCAL NAME & CONTACT INFO

unknown

Report by:

Philip Martin

Jamaica.heritage@yahoo.com

Osborn Store, Clarendon

Www.jamaicaheritage.wordpress.com

Location at Town Center on the market roof. N18.39280° W-077.36726° Elevation 435 meters Age: unknown. The market building is built on cast iron columns.

General Conditions

- 1) Not in operating condition for several years, general condition very poor.
- 2) Clock motor needs cleaning and repair or replacement.
- 3) The three dial gearboxes need cleaning and service.

Possible remediation:

- 1) Clean, oil and replace and repair in position and test the results.

