

October 2011 Inspection Report Highgate, St. Mary Tower Clock

LOCAL NAME & CONTACT INFO

Un Known

Report by:
Philip Martin
Jamaica.heritage@yahoo.com
Osborn Store, Clarendon

Location at town center of Highgate, St Mary. N18.27166° W-076.89077°
Elevation 293 meters. The clock has not operated for twenty years. There are three dial faces. Date erected unknown. There appears to be some type of engine but there is not an interior ladder. The entrance door is missing and there is free access.

General Conditions

- 1) General conditions unknown until inspection is preformed.
- 2) Not operating at this time due to unknown reasons.
- 3)
- 4)

Suggested Actions:

- 1) Un known until full inspection.
- 2) Repair Roof, and replace entrance doors.
- 3) Repair lightning rod system.
- 4) Needs exterior painting.



Entrance Door Non Existent



Interior View