October 2011 Inspection Report Falmouth Parish Church, Falmouth Trelawny Clock

LOCAL NAME & CONTACT INFO

Un Known

Location at Duke and King Streets Falmouth, Trelawny. N18.49321° W – 077.65685°. Elevation 6 meters. This clock is not working at this time. Has three dials. Built between 1794 and 1796. This is a beautiful structure and clock in urgent need of restoration.

Report by: Philip Martin Jamaica.heritage@yahoo.com Osborn Store, Clarendon

General Conditions

1) General conditions unknown until inspection is preformed.

2)



Suggested Actions:

1) Un known until full inspection. Internal repair of clock engine is obvious.

21

3)

4)









